
PEROPT POOLINENTATION DAGE					Form Approved
REPORT DOCUMENTATION PAGE Outsile reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instruction					OMB No. 0704-0188
Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing this collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.					
1. REPORT DATE (DD 22-09-2003	-MM-YYYY)	2. REPORT TYPE Technical Viewgraph		3. 1	DATES COVERED (From - To)
4. TITLE AND SUBTITLE				5a.	CONTRACT NUMBER
Investigating the Strain Rate Effects on Cumulative Damage in a Highly Filled Polymeric Material					GRANT NUMBER
				5c.	PROGRAM ELEMENT NUMBER
6. AUTHOR(S) C.T. Liu (AFRL/PRSM)					PROJECT NUMBER 02
					5e. TASK NUMBER 0378
				5f.	WORK UNIT NUMBER
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)					PERFORMING ORGANIZATION REPORT IMBER
Air Force Research Laboratory (AFMC) AFRL/PRS 5 Pollux Drive Edwards AFB CA 93524-7048					FRL-PR-ED-VG-2003-238
9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES)					SPONSOR/MONITOR'S ACRONYM(S)
Air Force Research Laboratory (AFMC) AFRL/PRS				11.	. SPONSOR/MONITOR'S
5 Pollux Drive Edwards AFB CA 93524-7048					NUMBER(S) FRL-PR-ED-VG-2003-238
12. DISTRIBUTION / AVAILABILITY STATEMENT					
Approved for public release; distribution unlimited.					
13. SUPPLEMENTARY NOTES					
For presentation at the International Conference on Mechanics of Time-Dependent Materials taking place in Lake Placid, NY, from 7-10 October 2003. 14. ABSTRACT					
15. SUBJECT TERMS				200	31017 121
	NINI O A PLANT		47 1111111111	40 11111	Lac NAME OF PROPERTY.
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON Leilani Richardson
a. REPORT	b. ABSTRACT	c. THIS PAGE	A	14	19b. TELEPHONE NUMBER (include area code)
Unclassified	Unclassified	Unclassified			(661) 275-5015 Standard Form 298 (Rev. 8-98) Prescribed by ANSI Std. 239.18

Investigating the Strain Rate Damage in a Highly Filled Effects on Cumulative Polymeric Materia

C. T. Liu

Air Force Research Laboratory 10 East Saturn Boulevard Edwards AFB CA 93524-7680, U.S.A.



Approved for Public Release; Distribution Unlimited

Objective:



Investigate Cumulative Damage in a Highly Filled Polymeric Material under Constant and Dual-Displacement Rate Loading Conditions.

Constant Displacement Rates: 0.02, 0.2, 2, 20 cm/min


Dual-Displacement Rate:

0.02 cm/min – 20 cm/min

• 0.2 cm/min – 20 cm/min


• 20 cm/min – 0.02 cm/min

























Phenomenological Damage Parameter Dp: $D(t) = \int_0^t dt dt$


Micromechanics Damage Parameter Dm

Damage Potential Function: $F = f(\epsilon_{ij}) \cdot K$

Damage Evolution Law: dDm/dt = [dK/dt] g (E)








































Damage Parameter, D_p








Volume Dilatation, %









Conclusions:



- For a given time, displacement rate has a significant effect on the damage intensity.
- The critical damage intensity is insensitive to the displacement rate and loading history.
- A good correlation exists between damage intensity and volume dilatation.
- The phenomenological damage parameter correlates well with the micromechanics damage parameter